

لاستیک بارز کردستان (شرکت سهامی خاص)

وابسته به گروه صنعتی بارز صندوق پستی: ۷۷۸۵-۱۵۸۷۵ کد پستی: ۳۳۴۲۱-۱۵۵۹۹

دفتر مرکزی:

تهران، خیابان سهروردی شمالی، خیابان هویزه شرقی، شماره ۵۲

تلفن: ۸۸۵۰۵۷۷۹ ۸۸۵۰۵۷۷۵ (۰۲۱) داورنگار: ۸۸۱۷۶۹۲۶ (۰۲۱)



AIR COMPRESSOR SCHEDULE

Designation	Type	QTY	Location	Normal Air Cap. (m3/min)	Free Air Cap. (m3/min)	Working Pressure (bar)	Site Condition			Cooling Water		Electrical Data		
							Elevation (m)	Inlet Temp. (C)	W.B. Temp (C)	Temp. In/Out (C)	Quantity (m3/hr)	V_φ-Hz Power (KW)		
Cent.A.Comp._01 &02	Centrifugal Air Comp.	2	Compressor Room Ext. Area	58	85	8.5	1934 Above See Level	-10~35	-10~35	27/37 ***	50~80 ***	3300-3-50 500 KW ***	380-3-50 30 KW ***	220-1-50 5KW ***

\*\*\* Should be finalized by vendor.

Air Filters Schedule

Designation	Type	QTY	Location	Air Cap. (m3/min)	Pipe Conn. (inch)	Working Pressure (bar)	Design Pressure (bar)	Particle Removal (micron)	Remarks
PF-01	Pre Filter	2	Compressor Room Before Dryer	85	5	10	16	<0.1	---
AF-01	After Filter	2	Compressor Room After Dryer	85	5	10	16	<0.1	---

Air Receivers Schedule

Designation	Type	QTY	Location	Capacity (Lit)	Diameter (cm)	Height (cm)	Thickness (mm)	Working Pressure (bar)	Design Pressure (bar)	Remarks
C.A.T-04&05	Vertical	2	Compressor Room Ext. Area	10000	165	450	12	10	16	---

Desiccant Air Dryer Schedule

Designation	Type	QTY	Location	Air Cap. (m3/min)	Weight (Kg)	Working Pressure (bar)	Electrical Data		Dimension L*W*H mm	Pipe Conn. Size	Remarks
							Power (KW)	V_φ-Hz			
Air Dryer_01&05	Absorption	2	Compressor Room Ext. Area	90	4000	10	72	380-3-50	2500*2500*3400	6	Heatless

Handwritten signature and blue official stamp of the company.

کارخانه:

سنندج، شهرک صنعتی دهگلان

تلفن: ۳۵۱۵۵۰۶۲ (۰۸۷) داورنگار: ۳۵۱۵۵۰۶۱ (۰۸۷)

Web site://www.barez.com

E-mail:info@barez.com