




12.5/



Technical requirement

- 1. Remove burrs and flash.
- 2. The acute angle is blunt.
- 3. The chamfers not marked are all 1× 45.

| | | | | | | | | | |
|-----------|--------------|-------------------|-------------------------|---|----------|------------------|---------------|--------------|------------------------------------|
| 2 | 030070135155 | | | Plate II | 1 | Q235A | 0.2 | 0.2 | |
| | | | | | | | | | |
| 1 | 030070613933 | | | Plate I | 1 | Q235A | 0.6 | 0.6 | |
| | | | | | | | | | |
| No. | Code | | | Part Name | Qty | Material | Single Weight | Total Weight | Remark |
| | Code Number | | | | | | Weight | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| Mark | Number | Modified file No. | | Signature | Date | MESNAC CO. , LTD | | | Cylinder block |
| Designer | | | Standarder | | 20180316 | | | | |
| Checker | | | Approver | | 20180316 | Mark | Weight | Scale | 020102LS0000159 TXJ0211AC.06.02 |
| Verifier | | | Security Classification | | 止 | A | 0.8 | 1:2 | |
| Processor | | | View |  | | Total No. No. | | | |